

All-Terrain Quality Improvements

GROVE

CM 6400





68.9 10



Product quality improvement

Dear customer,

At Manitowoc we work to constantly improve the quality of our cranes and to deliver highquality and reliable products to our customers.

Our goal is to implement new quality improvements as well as stringently adhering to our already existing quality standards.

Through the analysis of our customer surveys, we can continuously achieve new quality improvements and optimize the quality of our products.

We welcome any feedback that you have that will help us continue to improve our products even further!



Table of contents

Торіс	Crane model
 Spotlights 	All GMK
Fuel-filling	GMK5115, GMK5135, GMK5165-2
Cannon plugs	All GMK
Display	All GMK
Hook block stowage rope	All GMK
Boom nose reeving	GMK6300L
 Counterweight platform 	GMK4100B
Protected hydraulic tubes	All GMK
 Grab handle – upper cab 	All GMK
 Auxiliary hoist 	GMK6400
 Heat protection of steering cylinders 	GMK5225, GMK5275
 Air conditioner filling 	All GMK
 Wax protection 	All GMK
Steering	GMK5225, GMK5275

Table of contents

Торіс

- Proximity switch protection
- Rear view camera
- Rotating LED warning light
- Hose drum frame
- Striping
- Slewing ladder
- Rope guide
- Mirror extensions
- Striping for outriggers
- Outrigger pads
- Cases for documents and keys
- Split hook block
- Door lock

Crane model

GMK4100B

GMK6300L, GMK6400

All GMK

GMK6300L

All GMK

All GMK

GMK6300L, GMK6400

GMK with a Mercedes cab

All GMK

GMK4100B, GMK4115, GMK4115L

All GMK

All GMK

GMK6300L, GMK6400

Table of contents

Торіс	Crane model
Valve blocks	All GMK
 Zinc-nickel fittings 	All GMK
► Scale	All GMK
Anemometer holder	All GMK except GMK7550
 Additional corrosion protection for sea freight 	All GMK

Spotlights












Fuel-filling







Access to the fuel tank was difficult. A larger cutout facilitates easier fueling.

Cannon plugs









Display







All GMK

The display buttons were improved and anti-fog coating was added to the display.

Hook block stowage rope







All GMK

Protective sleeve added to the hook block stowage rope to minimize hook block damage.

Boom nose reeving









There is an additional connection point for the rope, reducing the distance to connect the ropes (example with two-part reeving).

Counterweight platform









Through a longer counterweight centering post, the superstructure parts are better protected and the mounting of the counterweight is easier.

Protected hydraulic tubes







Better corrosion protection through the usage of plastic coated hydraulic tubes.


Grab handle – upper cab








Auxiliary hoist








Lashing eyes were mounted on the auxiliary hoist.

Heat protection of steering cylinders







The heat protection of the steering cylinders was improved by implementing a heat protection plate.

Air conditioner filling






All GMK

Automated air conditioner refrigerant filling.

Wax protection







All GMK

All cranes receive a protection wax treatment before delivery. It is a solvent free, waterdilutable product for corrosion protection.

Steering







Flow Divider

Pressure Control Valve

GMK5225, GMK5275

The steering was improved through changing the flow divider and the pressure control valve.

Proximity switch protection





Service Bulletin D11-026

PARTS REQUIRED protection plate socket head screw M8 x 40 hexagon nut

GMK4100B

The proximity switches could easily be damaged while mounting. The switches are now better protected by a plastic cover.

Rear view camera





Version 1.03.00



GMK6300L, GMK6400

A software improvement was implemented to switch between work mode and rear view camera.

Rotating warning light LED












High power consuming beacon light was replaced by a new LED light with high efficiency and long life.

Hose drum frame







Frame Hydraulic drum



New fixture developed to eliminate hose reel handling damage.

Striping









All GMK Relocated striping decals for improved visibility.

Slewing ladder







Rope guide







Mirror extensions





All GMK with a Mercedes cab

The field of vision was improved by the new mirror extensions.

Striping for outriggers




All GMK The quality of the striping decals for the outriggers was improved.

Outrigger pads











> GMK4100B, GMK4115, GMK4115L

The new outrigger pads freely pivot and the guide rail was improved. They are available in steel and plastic.


Cases for documents and keys







Split hook block





We now offer split hook blocks which increase the versatility of the block for different applications. It allows the operator to adjust the weight of the block to correspond with the appropriate parts of line.

Door lock
















Valve blocks







Better corrosion protection through painted valve blocks.

Zinc-nickel fittings





All GMK Better corrosion protection through the use of zinc-nickel fittings.





All GMKs are weighed prior to shipment on a new scale inside our factory. This ensures consistent weight results.

Anemometer holder





Service Bulletin D13-013

All GMK except 7550

The anemometer holder is now placed in a space-saving storage box under the superstructure cabin, which protects the plugs and provides better protection against theft.

Additional corrosion protection for sea freight









All GMK

Each GMK is coated with a corrosion protection liquid prior to arrival at the port. The yellowish protective coating protects the components from the harmful effects of overseas transport. Upon delivery, the coating can be removed by cleaning with warm water. Currently, this additional corrosion protection is standard on all cranes transferred from Bremerhaven. Additional ports will be added to this program in 2014.

Notes

Notes



We are only satisfied if you are!



www.manitowoccranes.com January 2014 14-003